

ANALYSIS OF THE REASON WHY THE CLOTH LASER CUTTING MACHINE HAS NO LASER OUTPUT

Posted on 2023-07-31 by redsail

REDSAIL CM1390E LASER ENGRAVING/CUTTING MACHINE

2-Way Pass-Through
Professional Laser Machine Manufacturer

[VIEW MORE](#)



Category: [Laser Cutter News](#)



Analysis of reasons for no laser output of cloth [laser cutting machine](#)

Whether the focal length of the equipment is changed: adjust the focal length from the beginning.

Whether the collecting mirror is polluted: clean the collecting mirror.

Whether the optical path is offset: carefully adjust the optical path.

Whether the reflective lens is polluted or damaged: clean or replace the reflective lens.

Whether the cooling water circulates: dredge the cooling water.

Whether the cooling water quality or water temperature is normal: replace the clean cooling water to bring the temperature to the normal value.

Whether the laser power supply of the laser cutting machine is powered on: check the power supply circuit of the laser power supply to make it normal.

Whether the laser tube is damaged or aging: replace the laser tube.

Whether the laser power supply is damaged: replace the laser power supply.

Is the temperature of the whole machine too high?

(1) Shut down to let the temperature drop;

(2) Ventilation enhances heat dissipation of the machine;

(3) Adjust the ambient temperature.