WHAT ARE THE PRECAUTIONS AND USAGE SKILLS OF LASER CUTTING MACHINE

Posted on 2023-07-17 by redsail



Category: Laser Cutter News



When using a laser cutting machine, it is necessary to pay attention to some small details and precautions. Only by mastering the use skills can the processing efficiency of the equipment be higher. The following Redsail laser will give you a detailed introduction:

What are the precautions and usage skills of laser cutting machine

- 1. Corner melting; when cutting the corner of the thin plate at a reduced speed, the laser will melt the corner due to overheating. A small radius is generated at the corner to maintain the highspeed cutting of the laser and avoid the phenomenon of overheating and melting of the steel plate when cutting the corner, so as to achieve good cutting quality, reduce cutting time and improve manufacturing force.
 - 2. Spacing between parts: Usually, when cutting thick plates and hot plates, the distance between parts should be large. Since the heat of the thick plates and hot plates is greatly affected, it is easy to burn edges when cutting sharp corners and small graphics, which will affect the cutting quality.
- 3. Lead setting; in the process of cutting thicker plates, in order to make the slits well connected and prevent burns at the beginning and end, a transition line is often drawn at the beginning and end of cutting, which are called lead and tail respectively. Lead and tail The wire is useless to the workpiece itself, so it should be arranged outside the scope of the workpiece, and at the same time, be careful not to set the lead wire in a place that is not easy to dissipate heat, such as a sharp corner. The connection between the lead wire and the slit adopts a circular arc transition as much as possible to make the mechanical movement stable and avoid burns caused by corner stop.
 - 4. Co-edge cutting: combine two or more parts into a combination, and try to co-edge large quantities of regular graphics. Co-edge cutting can greatly shorten the cutting time and save raw materials.
- 5. Collision of parts; in order to increase production efficiency, some laser cutting machines run 24 hours a day, and use unmanned automatic loading and unloading devices to hit the overturned parts after cutting, causing damage to the cutting head and interruption of manufacturing, resulting in It's a big loss. When you need to sort, pay attention to the following three points:
 - 6. Choose an appropriate cutting path, avoid the cut parts, and reduce collisions.

- 7. Plan the cutting route reasonably to reduce the cutting time.
- 8. Automatically or manually combine multiple small parts with tiny connections. After cutting, the removed parts can easily disconnect the tiny connections.

In order to achieve a better operating state of the laser cutting machine, regular maintenance is also essential. The maintenance of the laser cutting machine should pay attention to the following points:

- 1) Check the straightness of the track and the verticality of the machine every six months, and maintain and debug in time if abnormalities are found. Avoid affecting the cutting effect, increasing the error will lead to a decrease in cutting quality.
 - 2) Check the steel belt frequently to make sure it is tight. Avoid problems during operation and accidental injury.
- 3) Once a week, use a vacuum cleaner to suck off the dust and dirt in the machine, and all electrical cabinets should be tightly closed to prevent dust.
- 4) Each guide rail should be cleaned frequently to remove dust and other sundries to ensure the normal operation of the equipment. The rack should be wiped frequently and lubricated to ensure lubrication without debris. Guide rails and motors should be cleaned and lubricated frequently, so that the machine can move better during travel, cut more accurately, and the quality of cut products will improve.
- 5) The dual focal length laser cutting head is a vulnerable item on the laser cutting machine. Longterm use may easily cause damage to the laser cutting head.