


PRECAUTIONS FOR LASER CUTTING MACHINE OPERATION

Posted on 2023-06-07 by redsail



Category: [Laser Cutter News](#)



1. Comply with the general safety operating rules of the cutting machine. Strictly follow the laser startup program to start the laser, adjust the light, and test the machine.



laser cutting machine

2. Operators must undergo training, be familiar with cutting software, equipment structure and performance, and master relevant knowledge of operating systems.
3. Wear labor protection equipment according to regulations, and wear protective glasses that meet regulations near the laser beam.
4. Before determining whether the material can be irradiated or cut by laser, do not process the material to avoid potential hazards such as smoke and steam generation.
5. When the equipment is started, operators are not allowed to leave their posts or be managed by entrusted personnel without authorization. If it is necessary to leave, the operator should stop the

machine or cut off the power switch.

6. If any abnormalities are found during the processing, they should be immediately stopped, and faults should be promptly eliminated or reported to the supervisor.