


WHAT ARE THE PRECAUTIONS FOR LASER CUTTING MACHINE OPERATION?

Posted on 2023-06-12 by redsail



Category: [Laser Cutter News](#)





Laser cutting machine

1. Follow the general rules for safe operation of cutting machines. Strictly follow the laser start-up procedure to start the laser, adjust the light, and test the machine.
2. Operators must be trained, familiar with cutting software, equipment structure and performance, and master the relevant knowledge of the operating system.
3. Wear labor protection articles according to the regulations, and wear protective glasses that meet the regulations near the laser beam.
4. Before determining whether the material can be irradiated or cut by laser, do not process the material to avoid the potential danger of smoke and steam.
5. When the equipment is started, the operator shall not leave the post without authorization or be managed by the entrusted person. If it is really necessary to leave, the operator should stop the machine or cut off the power switch.
6. If abnormalities are found during processing, stop immediately, troubleshoot or report to the supervisor in time.